

# CE-IDXPC(B) Install Guide

## Included Items:


- Pendant Cap x1
- Conduit Screw Connector x1

## Required Items:

- IDX Camera w/ Mounting Plate
- 3/4" Conduit or Camera Pole
- Phillips Screwdriver


### 1. ATTACH CONDUIT SCREW CONNECTOR

Attach the Conduit Screw Connector to a 3/4" Conduit Pipe or Camera Pole and tighten the screw to secure the connector to the pipe.




### 2. ATTACH PENDANT MOUNT CAP

Feed the power/video cables through the Pendant Cap and screw the Pendant Cap to the Conduit Screw Connector by turning clockwise.




### 3. CONNECT CABLES

Connect the power/video cables to the power/video cables on your IDX Camera. Feed any slack into the conduit pipe and Pendant Cap.



### 4. SECURE CAMERA TO PENDANT CAP

Secure the camera to the Pendant Cap by turning the camera clockwise until it locks in place.



## 5. ATTACH DOME COVER

Attach the dome cover to the camera by turning the cover clockwise until it locks into place.

